

COVERSHEET

Planned document changes:

Briefly:
No planned changes.

Document changes:

Date:	Change:	Rev. after change:
2026-04-09	EC added.	A
2025-09-29	New document.	-

Readers note:

 Indicates instruction.

 Represents Hose.

Dashed lines for overview, mounts
on other pages/assemblies.

Photos on page 3, 2 / 3

Std. Hitch components - S80

POS in order of assembly

Sensor Cylinder

EC333, Machine hitch

POS	DESCRIPTION	PART	QTY	COMMENTS
1	Inductive sensor QSM	1048262	2	EC: to slip ring. Machine: to Y-split
5	Set Screw M8x16	610808	1	
17	Sensor plate	1035535	1	Assemble with sligth play
31	In machine hitch sensors positions varies per control system			See "Machine hitch" for photos

Photo needed: Cylinder with sensor and sensor plate, seen from above

Sensor Hook EC

Photo needed: Sensor and set screw in EC hitch/hook

31

Sensor Cables EC

Photo needed: Sensors/sensor cables connected to slip ring