

engcon[®]

SPARE PARTS

Tiltcyl EC226 CC125/SL287 (1017719)	
Published:2013-01-24	Drawing No:1020731/-

COVERSHEET

Planned document changes:

Spherical bearing between POS.5 and POS.10 should be "9" instead of "5". Add POS.9 in partslist: 620113.

Tiltcyl EC226 CC125/SL287 (1017719)

Published: 2013-01-24

Drawing No: 1020731/-

POS	DESCRIPTION	PART	QTY	COMMENTS
5	Kolvstång	1017721	1	
6	Kolv	750419	1	
7	Toppmutter	1017114	1	
8	Tätningssats	750269	1	
10	SGH 62	640219	1	
11	Slangskydd	1014280	1	
12	Bricka Nordlock M8	611040	4	
13	Skruv M6S 8 x 16	610122	4	

