

Hydraulic system EC05

Published: 2015-06-10

Drawing No: 403181/G

COVERSHEET

Discontinued model/configuration, exploded view will receive no updates.

Notable regarding spare parts:

POS.2 is incorrect, correct item no: 710901.

POS.6 was replaced by 720116, use o-rings 710961 and screws 611202.

Sealings for POS.7: 710911 & 710912.

POS.17 was replaced by 710135.

Hydraulic system EC05

Published: 2015-06-10

Drawing No: 403181/G

POS	DESCRIPTION	PART	QTY	COMMENTS
1	Directional Valve EC05	730122	3	12V double
2	O-ring	710960	16	
3	Valveblock Motor	200592	1	
4	Socket Head Screw 8x65	610442	4	
5	O-ring 18x2 EC05 motor	710955	2	
6	Hydraulic Motor	720107	1	
7	Y-Plug valve block EC05	402153	1	
8	Bulkhead adapter 1260-04-04	710240	2	
9	Adapter	710106	2	
10	Hydraulic Hose	740511	1	
11	Hydraulic Hose	740510	1	
12	Washer Tredo	710703	2	
13	Valve block with swivel EC05	301422	1	See subheading Valve blocks & Swivels for exploded view
14	Adapter 90°	710151	1	
15	Directional Valve EC05	730121	1	
16	Washer Tredo	710702	8	
17	Adapter	710104	4	
18	Banjo bolt	710271	1	
19	Tilt cylinder EC05	400552	1	See subheading Tilt cylinders for exploded view
20	Hydraulic Hose	740520	1	
21	Hydraulic Hose	740521	1	
22	Hydraulic Hose	740519	1	
23	Hydraulic Hose	740514	1	
24	Non-return valve NRSM3/8	730212	1	
25	Carrier EC05 grab	404999	1	
26	Hex Head Screw 8x16	610710	2	
27	Screw MC6S 12x100	610488	4	Part of rotator frame assembly

